

# Data Insights from an Offshore Wind Turbine Gearbox Replacement


---

Alexios Koltsidopoulos Papatzimos<sup>1,2</sup>  
Tariq Dawood<sup>2</sup>  
Philipp R. Thies<sup>3</sup>

<sup>1</sup>*Industrial Doctorate Centre for Offshore Renewable Energy (IDCORE), Edinburgh, EH9 3JL*

<sup>2</sup>*EDF Energy R&D UK Centre, London, CR0 2AJ*

<sup>3</sup>*University of Exeter, Cornwall, TR10 9FE*



# Contents

---

1. Introduction and Motivation
2. Wind Turbine Gearbox Failures
3. Wind Turbine Gearbox Monitoring
4. Data Pre-processing
5. Failure Detection & Diagnosis
6. Data-Driven Models
7. Conclusions & Future Work



# 1. Introduction and Motivation

## Introduction- EDF Group Offshore Assets


- Teesside Offshore Wind Farm
  - 27 2.3MW turbines
  - 1.5 km offshore
  - 7-15m water depth
  - Installation completed in June 2013
- Blyth Demonstrator Project
  - 5 Vestas 8.3MW turbines
- Future assets
  - Totalling 1.5GW




## Motivation

- Gearbox replacement @ Teesside
- Gearboxes are designed to last for the lifetime of the asset- IEC 61400-4
- Majority of onshore and offshore wind turbines have a geared drivetrain
- Currently largest installed wind turbine (V164-8.0 MW) has a gearbox
- Early detection by OEM
  - Reduce downtime
  - Reduce component lead time
  - Understand component reliability
- Perform future fault prediction and diagnosis

## 2. Wind Turbine Gearbox Failures




[1]




[2]

## 2. Wind Turbine Gearbox Failures



[1]



[1]

## 2. Wind Turbine Gearbox Failures



Most common failure causes [3, 4]:

- Fundamental gearbox design errors
- Manufacturing or quality issues
- Underestimation of operational loads
- Variable and turbulent wind conditions
- Insufficient maintenance

Most common failure locations [4-8]:


- HS Bearing
- IMS bearing
- Planet bearing

Most common failure modes:






## 2. Wind Turbine Gearbox Failures



# 3. Wind Turbine Gearbox Monitoring


- SCADA
  - Temperature, pressure, vibration, current, rotational speed, etc.
    - Timeseries
- CMS
  - Vibration
    - Sampling in time instances
    - Pre-processed (Envelopes, FFTs, Cepstrum, RMS, etc)
  - Oil Particle Counter







## 4. Data Pre-processing

### Filtering




SCADA Alarms + maintenance log timestamps have been removed that include:

Yaw, Pitch, Generator, Electrical, Grid, Sensor failures, Environmental conditions, Maintenance operations




Savitzky–Golay filter



# 4. Data Pre-processing

## Filtering

Filtered Power Curve




Bins



IEC 61400-1-22


Binned Power Curve




# 5. Failure Detection & Diagnosis

## SCADA


Active Power vs Rotor Velocity




High Speed Temperature vs Active Power



Gearbox Oil Temperature vs Active Power





Gearbox Oil Temperature vs (Rotor Velocity)<sup>2</sup>



# 5. Failure Detection & Diagnosis


## SCADA




# 5. Failure Detection & Diagnosis

CMS

Planet Bearing Envelope



Planet Bearing FFT







# 5. Failure Detection & Diagnosis

CMS


Planet Bearing Cepstrum RMS



Particle Counter




# 5. Failure Detection & Diagnosis



## 6. Data-Driven Models

### SCADA

- “Healthy” state for data 4 months after replacement (orange)
- “Warning” state for data 4 months prior to replacement (blue)




Algorithm	Specifications	True Pos. (Healthy)	True Positive Rate (Warning)
SVM	Gaussian, Scale:0.26	97%	92%
Ensemble	Bagged Trees, Split: 10, learners: 30	96%	91%
KNN	Mahalanobis, NN=10	96%	92%
Decision Tree	Gini's index, max number of splits: 400	95%	86%
SVM	Quadratic, box constraint: 1	93%	81%

## 6. Data-Driven Models

### CMS

- Not constantly monitored systems
- Automation of forecasting models
- Autoregressive model for RMS signal
  - Predicted same slope for 26 out of 27 turbines



# 7. Conclusions and Future Work


---

## Conclusions

- Planet stage bearing spalling on a 3-stage 2.3MW turbine gearbox
- Similar studies investigated catastrophic gearbox failures
- Identify and diagnose the failure by using SCADA and CMS data
  - Temperature readings
  - RMS vibration
- Data driven models to predict future failures

## Future Work

- Further test the models in other failure modes and wind turbine models
- Investigate the environmental conditions' impact on the results






# References

---

- [1] Carroll J, McDonald A and McMillan D 2016 Failure rate, repair time and unscheduled O&M cost analysis of offshore wind turbines *Wind Energy* **19** 6 1107-19
- [2] Koltsidopoulos Papatzimos A, Dawood T and Thies PR 2017 An integrated data management approach for offshore wind turbine failure root cause analysis *Proc. 36th Int. Conf. on Ocean, Offshore and Arctic Engineering* (Trondheim) vol. 3B (New York: ASME)
- [3] Qiu Y, Chen L, Feng Y and Xu Y 2017 An Approach of Quantifying Gear Fatigue Life for Wind Turbine Gearboxes Using Supervisory Control and Data Acquisition Data *Energies* **10** 1084
- [4] Musial W, Butterfield S, McNiff B 2007 Improving Wind Turbine Gearbox Reliability *European Wind Energy Conference*
- [5] Nejad AR, Gao Z, Moan T 2014 Fatigue Reliability-Based Inspection and Maintenance Planning of Gearbox Components in Wind Turbine Drivetrains *Energy Procedia* **53** 248-57
- [6] Nejad AR, Gao Z and Moan T 2015 Development of a 5MW reference gearbox for offshore wind turbines *Wind Energy* **19** 6 1089–1106
- [7] McVittie D 2006 *Wind turbine gearbox reliability* Online: <https://goo.gl/gqLSv8>
- [8] Smolders K, Long H, Feng Y and Tavner PJ 2010 Reliability Analysis and Prediction of Wind Turbine Gearboxes *Proc. European Wind Energy Conference* (Warsaw: EWEA)
- [9] [https://www.gearboxfailure.com/wp-content/uploads/2016/07/MicropittingOn\\_Misaligned\\_Gear.jpg](https://www.gearboxfailure.com/wp-content/uploads/2016/07/MicropittingOn_Misaligned_Gear.jpg)
- [10] [http://media.noria.com/sites/archive\\_images/Backup\\_200101\\_Gear3.jpg?\\_\\_hstc=108323549.07430159d50a3c91e72c280a7921bf0d.1514764800116.1514764800117.1514764800118.1&\\_\\_hssc=108323549.1.1514764800119&\\_\\_hsfp=528229161](http://media.noria.com/sites/archive_images/Backup_200101_Gear3.jpg?__hstc=108323549.07430159d50a3c91e72c280a7921bf0d.1514764800116.1514764800117.1514764800118.1&__hssc=108323549.1.1514764800119&__hsfp=528229161)
- [11] <https://www.novexa.com/en/intervention/gears/defects-treated.html>
- [12] <http://www.rttech.com.au/wp-content/uploads/2010/06/mt6.jpg>

# Questions

---



[Alexios.Koltsidopoulos@edfenergy.com](mailto:Alexios.Koltsidopoulos@edfenergy.com)

## **Acknowledgement:**

This work is funded by the Energy Technology Institute and the Research Council Energy Programme as part of the IDCORE programme (grant EP/J500847).