

Example of documentation of results.

Ref	Question/ Weak points	Suggestions/Recommendations	Resp.
1.11	<p>Can the operator have a natural posture while seated at his workplace?/ <i>The operator's legs touch the lower part of the desk at the VDU work stations.</i></p>	The seating arrangement at the VDUs should be redesigned (desk/chairs).	Statoil/ Håkon Fartum
2.17	<p>Are glare and reflection from lighting avoided?/ <i>Ceiling lighting causes glare on the VDU screen.</i></p>	Lighting should be redesigned to avoid reflections on the VDUs.	Statoil/ Håkon Fartum
2.27	<p>Are vibrations in the control room within acceptable limits?/ <i>The control room is planned to be located below vibrating equipment.</i></p>	Increase distance between vibrating equipment and the control room, or initiate special measures.	Statoil/ Håkon Fartum
3.23	<p>Are suppression mechanisms used to reduce the number of consequence alarms during equipment / process shutdown?/ <i>Unnecessary alarms are not suppressed.</i></p>	Too many unimportant alarms divert the operators' attention from important alarms, and the operators may not have sufficient time to analyze the situation.	Statoil/ Håkon Fartum
3.40	<p>Are warnings provided if out-of-range values are entered?/ <i>There is no warning function for out-of-range values, and operators may enter wrong values into the system (e.g. 44000 instead of 4400).</i></p>	Warnings should be provided if out-of-range values are entered by the operators.	Statoil/ Håkon Fartum