Experience from RCM and RDS-PP coding for offshore wind farms

EERA DeepWind 2017, Trondheim 19th of January 2017



roger.sundal@maintech.no

Man forty-seven most uneven age ever

Roger Sundal



Reelle løsninger på reelle problem. Alltid.

www.maintech.no

#maintechkonferansen















52 655 Tags

609 Tags for each turbine

88 turbine

7531 transmissions Tags

RDS-PP on turbines

IEC 61346 on transmission assets



Reliability-Centered Maintenance



An analytical process used to determine appropriate failure management strategies to ensure safe and cost-effective operations of a physical asset in a specific operating environment.



Failure management can be to create preventive maintenance tasks, or to run the asset to failure




The main goal of RCM is to avoid or reduce failure CONSEQUENCES - Not necessarily to avoid failures

IEC 60300-3-11Application guide Reliability-Centered maintenanceSAE JA 1011Evaluation criteria for Reliability-Centered Maintenance processes




Distribution of tasks on task types






Failure management decision







88 similar turbines





Logistics are different offshore



▲ Consequence		<i>8</i> L	ink to •	🔀 Tilføy 📗	Redigér X Tilføy Ligne	nde 📕 Slett	t 📔 Statu	s 🐐 🕞 Redigér	🛃 Indikatorer 🕶 🦞	Filter •	līs ▼
	Ta ▲				Func Brkdwn						
Enction Breakdown	8 1			Function Id		Criticality 🔻		ag ld	Description	Parent	N
TR Substation	7.5		1		Structures in wind turbine syst	t <mark>10</mark>	2500.A01=U	JMD79BG001 Tw	vist monitoring system 2		
⊟ WT Windturbine	e		2		Blade adjustment			ADC11BG001 Ptt		500.A01=MDC11	_
🖻 🚘 WT01 Windturbine all groups	e		3		Blade adjustment	8		ADC12BG001 Pite		500.A01=MDC12	
😽 BG Position indicator	-		4		Blade adjustment	8				500.A01=MDC13	
BS Vibration sensor			5		Warning systems			(SD80BG001 GF		500.A01=XSD80	
🕀 🗠 BX Telephone			6	WT-WT01-BG						500.A01=MDL62	_
🗉 🗠 BZ Sensor, combined tasks			7		Rotor structure, Hub and Blac				measurer calibration 2		_
🛨 🗠 CM Accumulator, tank			8		Rotor structure, Hub and Blac				measurer calibration 2		
🗈 🗠 EA Lighting			9	W1-W101-BG	Rotor structure, Hub and Blac	a) (2500.A01=N	IDAT3BG001 Tip	measurer calibration 2	500.A01=MDA13	Statkr
EQ Cooler											
🕀 🗠 FM Extinguisher											
FQ Personal protection like r											
S Covers											
I → GA Generator											
⊕ GF Generate signal like tran											
GM Service crane, tackle											
🕀 🗠 GP Pump		•									
GT Lubrication		-				-					
HQ Filter element (mechanic		FME	CA Wo	rk Orders PI	M Program Recommended	Tasks RCM	I fra Norge				
HS Filter element (magnetic)		F	ilter • 📘	🛛 Vis 🕶 🛛 🛃 El	ksportér 🖶 Udskriv 🛛 🔀	<u>/</u> alg •					
3 V Filter					Sorting						CM del
S M Y Filter		E =8	Rekke	Function Id		Func		Failuremode		PF Interval	Pf Un
		•	1		Blade adjustment	Forbinder enco	-		Feil på måling og stor	pp	
			2		Blade adjustment	Tilbakemelde v			Redusert effekt		
E C System			3		Blade adjustment			Ledningsbrudd	Ingen regulering, stop		
Equipment Category			4		Blade adjustment			Defekt kompone			
🗈 🍪 Rough Sorting			5		Blade adjustment	Forbinde enco	-	Løs del	Feil på måling og stor	pp	
🕀 🐝 Equipment Group			6	¦‱T-₩T01-BG	Yaw system	Posisjonsgiver	yaw system	Defekt kompone	nt Stopp av vindmølle		
	_	_	1		Long Anna	Landa at			- I and be an or an		
E 🐺 Equipment Group			e	WT-WT01-BG					rt Stopp av vindmøle		
🗄 👯 Rough Sorting			5		Blade adjustment	Forbinde enco			Fel of main	Mai	nl
Equipment Category			4		Blade adjustment	Tilbakemelde v		Defekt kompone	at ingen regult (Irial	
C St planeur									ingen regulenne do		

Benefit from others work – apply a standard

RDS-PP – find your level

Remember: Failures you want to register on a low level, preventive work on a higher level



Thank you for your attention!



roger.sundal@maintech.no www.maintech.no #maintechkonferansen

